


Name of the Equipment	Walk-in Test Chamber
Purpose / Use	<ul style="list-style-type: none"> • Used to carry out Temperature and Humidity Test on subsystem/Systems • Confirming to MIL-STD-810F & JSS 55555
Photograph	
Key specification	<ul style="list-style-type: none"> • Working Space : 3.50x3.50x3.00 M • Temperature Range: : -40°C to 100°C • Relative Humidity : Ambient to 95%